


LIDCO MMA Vibration Measurements


Date: 3/12/07

Room/Location/Setup: Setup 1 Room 1-3

Operator: K. J. ... + ...



Run	Instrument	Time ON-	Time OFF	Comment
1		07:55	07:59:44	304 Area 1250 lbs W/interior FL of Room
2				#2 Window Club FLWIR
3				South of N. Stairway M/CYN
4				via line to West of BE of PS
5				" " West of BE
6				between column and 1st floor
Run 2		07:25:21	07:25:22	V46 7500 ft Obs
				same set-up
Run 3		07:36:08	07:37:08	V46 7500 ft Obs
				same set-up
				via line to 1st floor in fluid operation re back to full extent of operation




LDEO MMA Vibration Measurements

Date: 3/12/07


Room/Location/Setup: Setup 2

Operator: K. Decker + T. Lewis

by the North



Instrument	Time ON-	Time OFF	Comment
Run 1	10:14	10:23:17	V46
#1			
2			
3			
4			
5			
6			
Run 2	10:41:00	10:50	
			Some instrument lay out
			Some V46
			but not sure if working
			correctly




LDEO MMA Vibration Measurements


Date: 3/12/2007

Room/Location: #3 Bank Arcade

Operator: KH Jacobs - Ferris



Instrument	Time ON	Time OFF	Comment
Run 1	1:08:12	1:12:06	
# 1			Wood Cut Bay 1
# 2			Wood Cut Bay 2
# 3			MICY N. column base
# 4			Brick wall over Appl. Col
# 5			Brick wall over Appl. Col
# 6			Fireplace 3rd floor
Run 2	13:38:00	13:42:00	Additional floor sensor



03/12/2007

MMA Set-up #3

Run 1: 13:08:12 EDT. Run 2: 13:38:00 EDT
/ (Adrian turns one sensor on Bank facade)

View North

W
Central Park
←

E
5th Ave
→

